



2.2 Display Features

DMM 110



DMM 120 / DMM 140



AUTO	Auto range
•••)	Continuity
≡	DC mode
~	AC mode
—	Negative polarity
▶	Diode Test
P-HOLD	
HOLD	Data Hold
Hfe	
⊕	Low battery indication
kMΩ	
°C °F	Temperature selection
mVA	
μ	
RS232	
▲	
Hz%	Frequency Percentage

2.3 Button Functions

2.3.1 Data Hold Button

This function locks the present displayed value.

To activate, press and hold down the **DATA HOLD** button. Press once again to exit this function.

2.3.2 Range Button

This button is used to toggle between auto and manual ranging. By default, the meter is in the auto-ranging mode.

To enter the manual-ranging mode, press the **RANGE** button. The **AUTO** icon on the display will disappear.

To return to the auto-ranging mode, press and hold the **RANGE** button for 2s or more.

2.3.3 Select Button

This button is used to select different functions and ranges.

2.3.4 Auto-Off Function

The meter will shut down automatically approximately 30 minutes (DMM 120/140) or 15 minutes (DMM 110) of no activity.

To disable the Auto-Off function, press and hold down the **SELECT** button while turning the meter on.

2.3.5 Backlight

To turn the backlight ON, press and hold the **DATA HOLD** button for 2s or more. Press and hold again to turn the backlight OFF.

Note: When the **DATA HOLD** button is pushed to turn on the backlight, the Hold function is enabled. Press the **DATA HOLD** button again to release the Data Hold function.

SPECIFICATIONS

3.1 Electrical Specifications

*Accuracy given @ 23°C ± 5°C, 80% RH max

DC Voltage

DMM 110	DMM 120/140	Resolution	Accuracy	Input Impedance
200mV	400mV	0.1mV	0.5% ± 2cts	10MΩ
2V	4V	1mV		
20V	40V	10mV		
200V	400V	100mV		
600V	600V	1V		

AC Voltage (TRMS - Model DMM 140 only)

DMM 110	DMM 120/140	Resolution	Accuracy	Input Impedance
200mV	400mV	0.1mV	1.0% ± 4cts	10MΩ
2V	4V	1mV		
20V	40V	10mV		
200V	400V	100mV		
600V	600V	1V		

DC Amperes

DMM 110	DMM 120/140	Resolution	Accuracy
200μA	400μA	0.1μA	1.2% ± 2cts
2mA	4mA	0.001mA	
20mA	40mA	0.01mA	
200mA	400mA	1mA	
2A	4A	1mA	
10A	10A	10mA	

AC Amperes (TRMS - Model DMM 140 only)

DMM 110	DMM 120/140	Resolution	Accuracy
200μA	400μA	0.1μA	1.5% ± 4cts
2mA	4mA	0.001mA	
20mA	40mA	0.01mA	
200mA	400mA	1mA	
2A	4A	1mA	
10A	10A	10mA	

Resistance (Ω)

DMM 110	DMM 120/140	Resolution	Accuracy
20 Ω	40 Ω	0.01 Ω	1.0% \pm 3cts*
200 Ω	400 Ω	0.1 Ω	
2000 Ω	4000 Ω	1 Ω	
20k Ω	40k Ω	0.01k Ω	
200k Ω	400k Ω	0.1k Ω	
2M Ω	4M Ω	0.001M Ω	
20M Ω	40M Ω	0.01M Ω	

Continuity (\bullet ••)

DMM 110	DMM 120/140	Buzzer	Protection
200 Ω	400 Ω	<100 Ω (<10ms)	500V PTC

Diode (\rightarrow •)

DMM 110	DMM 120/140
0 to 2V	0 to 4V

Capacitance $\text{—}|$ (Model DMM 120/140 only)

Range	Resolution	Accuracy
40nF	0.01nF	3% \pm 3cts
400nF	0.1nF	
4 μ F	0.001 μ F	
40 μ F	0.01 μ F	
100 μ F	0.1 μ F	

Frequency - Hz (Model DMM 120/140 only)


Range	Resolution	Accuracy
40Hz	0.01Hz	0.2% \pm 2cts
400Hz	0.1Hz	
4000Hz	1Hz	
40kHz	0.01kHz	
400kHz	0.1kHz	
4Hz	0.01MHz	

Duty Cycle % (Model DMM 120/140 only)

0.1 to 99.9%, Accuracy 1% \pm 3cts

Digital display: 2000-count $3\frac{3}{4}$ digit LCD (DMM 110)
4000-count $3\frac{3}{4}$ digit LCD (DMM 120 and DMM 140)

Overload: If the range is exceeded, the OL symbol is displayed.

Low battery indicator:  is displayed when the voltage supplied by the batteries is lower than the operating voltage.

Power Supply: 2 Batteries – 1.5V type AA (LR6)

Fuse: 500mA, 250V (5x20mm)

Auto-Off: Automatic shut down after approx 30 minutes (DMM 120/140) or 15 minutes (DMM 110) of no use.

3.2 Environmental Specifications

Operating Temperature: 32° to 104°F (0° to 40°C)
80% RH max non-condensing

Storage Temperature: 14° to 122°F (-10° to 50°C)
80% RH max non-condensing, battery removed

Altitude: 6000 ft (2000m)

3.3 Mechanical Specifications

Dimensions: 1.38 x 3.07 x 5.84" (35 x 78 x 152mm)

Weight: 11.8 oz (330g) with holster

3.4 Safety Specifications

IEC/EN 61010, 600V Cat. II, 300V Cat. III



OPERATION

4.1 AC/DC Voltage Measurement ($\tilde{\sim}$ $\overline{\text{DCV}}$ $\overline{\text{DCmV}}$)

- Turn the rotary switch to the appropriate range.
- Insert the black test lead to the “COM” input connector and the red test lead to the “V” input connector.
- Connect the test leads to the device or circuit to be measured and read the data on the display.

Note: Autorange can be changed into manual operation by holding down the RANGE button for approx 2s.

4.2 AC/DC Current Measurement ($\overline{\mu\text{A}}$ $\overline{\text{mA}}$ $\overline{10\text{A}}$)

- Turn the rotary switch to the appropriate range.
- Insert the black test lead to the “COM” input connector (or 10A input connector if measurement is <200mA) and the red test lead to the “ μmA ” input connector.
- Connect the test leads to the device or circuit to be measured and read the data on the display.

4.3 Resistance Measurement (Ω)



WARNING: When making a resistance measurement, make sure that the power is off (dead circuit). It is also important that all capacitors in the measured circuit be fully discharged.

- Insert the black test lead to the “COM” input connector and the red test lead to the “ Ω ” input connector.
- Turn the rotary switch to the Ω range.
- Bring the test probe tips into contact with the sample under test and read the data on the display.

4.4 Continuity Test (••))



WARNING: When testing continuity, make sure that the power is off (dead circuit). Never apply voltage to the input terminals.

- Insert the black test lead to the “COM” input connector and the red test lead to the “Ω” input connector.
- Turn the rotary switch to the ••)) range.
- Bring the test probe tips into contact with the sample under test and read the data on the display.
- If the resistance is $<100\Omega$, the beeper emits a continuous sound.

4.5 Diode Test (➔|)



WARNING: Never apply voltage to the input terminals.

- Turn the rotary switch to the ➔| position.
- Insert the black test lead to the “COM” input connector and the red test lead to the “➔|” input connector.
- Touch the red lead to the anode of the diode and the black lead to the cathode of the diode.
- Read the voltage on the display.

4.6 Capacitance Measurement (|-|)



WARNING: Discharge any capacitors before testing


- Turn the rotary switch to the |-| position.
- Insert the capacitor leads into the capacitor test socket. Because there are two groups of holes, one lead must be inserted into the hole of one of the two groups and the other lead into the hole of the other group.
- Read the capacitance value on the display.

MAINTENANCE

5.1 Warning

- Remove the test leads from any input before opening the case. Do not operate the instrument without a battery case cover.
- To avoid electrical shock, do not attempt to perform any servicing unless you are qualified to do so.

5.2 Battery Replacement

- Replace the batteries when the  symbol appears on the display.
- The meter must be in the OFF position and disconnected from any circuit or input.
- Remove the two screws located near the bottom of the rear cover to remove the battery cover.
- Replace the old batteries with two new 1.5V AA (LR6) batteries.
- Screw the battery cover back on.

5.3 Cleaning

- To clean the instrument, wipe the case with a damp cloth and mild detergent. Do not use abrasives or solvents.
- Do not get water inside the case. This may lead to electrical shock or damage to the instrument.

5.4 Storage

- If the meter is not used for periods longer than 60 days, remove the batteries and store them separately.

Repair and Calibration

To ensure that your instrument meets factory specifications, we recommend that it be scheduled back to our factory Service Center at one-year intervals for recalibration, or as required by other standards or internal procedures.

For instrument repair and calibration:

You must contact our Service Center for a Customer Service Authorization Number (CSA#). This will ensure that when your instrument arrives, it will be tracked and processed promptly. Please write the CSA# on the outside of the shipping container. If the instrument is returned for calibration, we need to know if you want a standard calibration, or a calibration traceable to N.I.S.T. (Includes calibration certificate plus recorded calibration data).

Ship To: Multimetrix®
15 Faraday Drive
Dover, NH 03820 USA
Tel: (800) 945-2362 (Ext. 360)
(603) 749-6434 (Ext. 360)
Fax: (603) 742-2346 or (603) 749-6309
repair@multimetrix.com

(Or contact your authorized distributor)

Costs for repair, standard calibration, and calibration traceable to N.I.S.T. are available.

NOTE: You must obtain a CSA# before returning any instrument.

Technical and Sales Assistance

If you are experiencing any technical problems, or require any assistance with the proper operation or application of your instrument, please call, mail, fax or e-mail our technical support team:

Multimetrix®
200 Foxborough Boulevard
Foxborough, MA 02035 USA
Phone: (800) 343-1391
(508) 698-2115
Fax: (508) 698-2118
techsupport@multimetrix.com
www.multimetrix.us

NOTE: Do not ship Instruments to our Foxborough, MA address.

Limited Warranty

The Model DMM 120 and DMM 140 are warranted to the owner for a period of one year from the date of original purchase against defects in manufacture. This limited warranty is given by Multimetrix®, not by the distributor from whom it was purchased. This warranty is void if the unit has been tampered with, abused or if the defect is related to service not performed by Multimetrix®.

For full and detailed warranty coverage, go to www.multimetrix.us. The warranty information is located in our customer service section.

What Multimetrix® will do:

If a malfunction occurs within the one-year period, you may return the instrument to us for repair, provided you submit a proof of purchase. Multimetrix® will, at its option, repair or replace the faulty material.

Warranty Repairs

What you must do to return an Instrument for Warranty Repair:

First, request a Customer Service Authorization Number (CSA#) by phone or by fax from our Service Department (see address below), then return the instrument along with the signed CSA Form. Please write the CSA# on the outside of the shipping container. Return the instrument, postage or shipment pre-paid to:

Multimetrix®
Service Department
15 Faraday Drive • Dover, NH 03820 USA
Tel: (800) 945-2362 (Ext. 360)
(603) 749-6434 (Ext. 360)
Fax: (603) 742-2346 or (603) 749-6309

Caution: To protect yourself against in-transit loss, we recommend you insure your returned material.

NOTE: You must obtain a CSA# before returning any instrument.

Multimetrix®

08/04

99-MAN 100009 v1

Multimetrix® a division of Chauvin Arnoux®, Inc.
15 Faraday Drive • Dover, NH 03820 USA
www.multimetrix.us